

Ship Detail

Ship Name	SIDER AMY	Shiptype	General Cargo Ship
IMO/LR No.	9331505	Gross	9,177
Call Sign	MKWC7	Deadweight	13,538
MMSI No.	235010170	Year of Build	2006
Flag	Isle Of Man	Status	In Service/Commission
Operator	Nova Marine Carriers SA	Shipbuilder	Kyokuyo Shipyard Corp



Ownership

Group Owner	Unknown	Address Location	Company No.	9991001
Shipmanager	Nova Marine Carriers SA	Address Location	Switzerland	Company No. 5574477
Operator	Nova Marine Carriers SA	Address Location	Switzerland	Company No. 5574477
DOC Company	Nova Ship Tech SA	Address Location	Switzerland	IMO Company No (DOC) 5808479
Registered Owner	Bridge Shipping Ltd-GBI	Address Location	Switzerland	IMO Registered Owner No 5801410
Technical Manager	Nova Ship Tech SA	Address Location	Switzerland	Company No. 5808479
Bareboat Owner	Not Applicable	Address Location	Company No.	9984588

Ownership History

☒ Show extended history

Date	Name	Flag	Group Owner	Operator	Manager	Registered Owner	DOC	Price	Seq
2018-09			Unknown						00
2018-05	SIDER AMY								00
2018-01							Nova Ship Tech SA		00
2017-01					Nova Marine Carriers SA				00
2017-01				Nova Marine Carriers SA					00
2014-10		Isle Of Man							00
2014-06						Bridge Shipping Ltd-GBI			00
2014-06		United Kingdom							92
2014-06		Panama							93
2014-04								\$7,250,000	00
2008-07			Tachibanaya Co Ltd						95
2006-10							Carisbrooke Shipping Ltd		93
2006-10							Carisbrooke Shipping Mgmt Ltd		94
2006-06							Unknown		95
2006-05		United Kingdom							94
2006-05						Yaoki Shipping SA			95
2006-05					Carisbrooke Shipping Ltd				95
2006-05				Carisbrooke Shipping Ltd					95
2006-05		Panama							95
2006-05	Amy C								95

Originally Amy C

Registration, P&I, and Communications

Port of Registry	Douglas	Flag	Isle Of Man
Official Number	920011	Sat Com ID	
Sat Com Ans Back		Fishing Number	
Current P&I Club	Standard Club, The		

P&I Club History

Date	P&I Club
2017-01-24	Standard Club, The
2008-07-08	Charles Taylor & Co-Bermuda

Flag, Call Sign & MMSI History

Date	Flag	Port of Registry	Call Sign	MMSI
2014-10	Isle Of Man	Douglas	MKWC7	235010170
2014-06	United Kingdom	Cowes		
2014-06	Panama	Panama		
2006-05	United Kingdom	Cowes		
2006-05	Panama	Panama		

Three Year Event Summary

Significant Event	Last 12 months	Between 1 and 2 years ago	2-3 years ago
Casualties	0	0	0
Class status changes	0	0	3
Detentions	0	0	0
DOC certificates	0	0	3
Flag changes	0	0	0
Group Owner changes	0	0	1
Inspections	2	5	4
Name changes	0	0	1

Class

Class: Registro Italiano Navale (IACS) (2018-05-00), Class ID: 97215 RI: Special Survey Date: 2016-04-10 Class Notation: C+ General cargo ship - double side-skin - heavycargo AUT-UMS BWM-E - flow-through INWATERSURVEY MON-SHAFT Service Restriction: unrestricted navigation

Class History

Date	Class	Status
2018-05-09	Lloyd's Register	(Disclassed)
2018-05-00	Registro Italiano Navale (IACS)	(Contemplated)
2008-11-25	Lloyd's Register	In Class
2008-11-14	Lloyd's Register	(Transferred)
2008-11-00	Bureau Veritas (IACS)	(Disclassed)
2006-06-00	Bureau Veritas (IACS)	In Class
2004-04-00	Bureau Veritas (IACS)	(Contemplated)

Surveys

Special Survey Due 2021-05-10, Assigned 2016-04-10, Registro Italiano Navale
Docking Survey Due 2021-05-10, Assigned 2019-02-21, Registro Italiano Navale

Crew List

Data as of 2020-03-12

Nationality	Total Ratings	Total Officers	Total Crew
Filipino	8	0	8
Ukranian	2	4	6
Montenegrin	0	2	2

Inspections & Detentions

Data as reported by Port State Control Authorities <u>Paris MOU Data Feed Update</u>							
This ship is listed under the US Coastguard Qualship 21 Program							
Authority	Status	Date	Place	Name	Flag	Class	Owner
US Coastguard LE	Inspection	2020-08-30	Buffalo New York	Sider Amy	Isle Of Man	Registro Italiano Navale	
US Coastguard	Inspection	2020-08-28	Cleveland Ohio	Sider Amy	Isle Of Man	Registro Italiano Navale	
Vina Del Mar	Inspection	2019-09-07	CORTES	Sider Amy	Isle Of Man	Lloyds Register	Nova Ship Tech Sa.
US Coastguard	Inspection	2019-07-11	Houston Texas	Sider Amy	Isle Of Man	Lloyd's Register Of Shipping	
Vina Del Mar	Inspection	2019-05-15	BARRANQUILLA	Sider Amy	Isle Of Man	Lloyds Register	Nova Ship Tech Sa.
Vina Del Mar	Inspection	2019-03-22	BARRANQUILLA	Sider Amy	Isle Of Man	Lloyds Register	Nova Ship Tech Sa.
Vina Del Mar	Inspection	2019-03-21	BARRANQUILLA	Sider Amy	Isle Of Man	Registro Italiano Navale	Nova Ship Tech Sa.
US Coastguard	Inspection	2018-06-26	Miami Florida	Sider Amy	Isle Of Man	Lloyd's Register Of Shipping	
Paris MOU	Detailed Inspection	2018-03-07	Arhus	Amy-C	Isle Of Man (United Kingdom)	Lloyd's Register	
3 Defects: Fire safety - Fire pumps and its pipes - Inoperative Water/Weathertight condition - Cargo & other hatchways - Damaged Life saving appliances - Inflatable liferafts - Not ready for use							
Med MOU	Inspection	2018-01-09	Agadir	Amy C	Man, Isle Of	Lloyd's Register	
Paris MOU	Detailed Inspection	2017-10-24	Sorel	Amy-C	Isle Of Man (United Kingdom)	Lloyd's Register	
5 Defects: Propulsion and auxiliary machinery - Bilge pumping arrangements - Inoperative Fire safety - Fire-dampers - Inoperative Fire safety - Fixed fire extinguishing installation - Not as required Safety of Navigation - Bridge operation - Lack of familiarity ISM - ISM - Not as required							
Tokyo MOU	Inspection	2017-08-15	Coronel	Amy C	Isle Of Man (Gb)	Lloyd's Register	
1 Defect: Gauges,thermometers, etc							
Tokyo MOU	Follow up	2017-08-15	Coronel	Amy C	Isle Of Man (Gb)	Lloyd's Register	
US Coastguard	Inspection	2017-06-05	New York New York	Amy C	Isle Of Man	Lloyd's Register Of Shipping	
US Coastguard	Inspection	2016-12-19	Philadelphia Pennsylvania	Amy C	Isle Of Man	Lloyd's Register Of Shipping	
1 Defect: OPERATIONS/MANAGEMENT - POLLUTION							
Vina Del Mar	Inspection	2016-08-11	BARRANQUILLA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
Vina Del Mar	Inspection	2016-05-27	BARRANQUILLA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
Vina Del Mar	Inspection	2016-05-26	BARRANQUILLA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
3 Defects: Structural condition - Electrical installations in general (To be rectified before departure) Life saving appliances - Embarkation arrangements rescue boats (To be rectified before departure, To be rectified at next port of call) Propulsion and auxiliary machinery - Gauges,thermometers, etc (To be rectified before departure)							
Caribbean MOU	Inspection	2016-05-10	FORT DE FRANCE	Amy C	United Kingdom	Lloyd's Register	
1 Defect: Labour Conditions - Conditions of employment - Other (Conditions of employment) (To be rectified within 14 days)							
Paris MOU	Initial Inspection	2016-04-11	Nowy Port/Gdansk	Amy-C	Isle Of Man (United Kingdom)	Lloyd's Register	
2 Defects: Emergency Systems - Emergency, lighting,batteries and switches - Not as required Emergency Systems - Emergency, lighting,batteries and switches - Not as required							
US Coastguard	Inspection	2015-10-26	Miami Florida	Amy C	United Kingdom	Lloyd's Register Of Shipping	
Paris MOU	Initial Inspection	2015-05-25	Alcanar	Amy-C	Isle Of Man (United Kingdom)	Lloyd's Register	
Vina Del Mar	Inspection	2015-03-11	MEJILLONES	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
Vina Del Mar	Inspection	2015-03-05	CALLAO	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
Vina Del Mar	Inspection	2014-09-05	BARRANQUILLA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
2 Defects: Gauges,thermometers, etc (Master instructed to rectify deficiencies before d) Water, pipes, tanks (Master instructed to rectify deficiencies before d)							
Vina Del Mar	Follow up	2014-09-05	BARRANQUILLA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa

Authority	Status	Date	Place	Name	Flag	Class	Owner
2 Defects: Gauges,thermometers, etc (Deficiency rectified) Water, pipes, tanks (Deficiency rectified)							
Paris MOU	Detailed Inspection	2014-04-14	Lisboa	Amy-C	United Kingdom	Lloyd's Register	
1 Defect: Certificates & Documentation - Document - Oil record book - Not as required							
US Coastguard	Inspection	2014-02-05	New Orleans, Louisiana	Amy C	United Kingdom	Lloyd's Register Of Shipping	
2 Defects: ENGINEERING - FUEL OIL SERVICE SYSTEM PERSONNEL - TRAINING							
Caribbean MOU	Inspection	2014-01-21	DEGRAD DES CANNES	Amy C	United Kingdom	Lloyd's Register	
2 Defects: Water/Weathertight condition - Ventilators, air pipes, casings (To be rectified before departure) Propulsion and auxiliary machinery - Propulsion main engine (To be rectified within 14 days)							
Vina Del Mar	Inspection	2013-12-02	BUENAVENTURA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
Vina Del Mar	Inspection	2013-07-18	ANTOFAGASTA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
Vina Del Mar	Inspection	2013-01-31	ANTOFAGASTA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
5 Defects: Bilge Cleanliness (Deficiency rectified) Cleanliness of Engine Room (Deficiency rectified) Control Valves (Deficiency rectified) Portable Extinguishers / Non Fixed (Deficiency rectified) Hydrants (Deficiency rectified)							
Vina Del Mar	Inspection	2013-01-23	CALLAO	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
Vina Del Mar	Inspection	2013-01-03	CALLAO	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
2 Defects: Cleanliness of Engine Room (Rectify deficiency within 14 days) Portable Extinguishers / Non Fixed (Rectify deficiency within 14 days)							
Vina Del Mar	Inspection	2012-12-04	ARICA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
3 Defects: Bilge Cleanliness (Rectify deficiency within 14 days) Control Valves (Rectify deficiency within 14 days) Hydrants (Rectify deficiency within 14 days)							
Vina Del Mar	Inspection	2012-09-12	CALLAO	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
2 Defects: Spare Charges for Self Contained Breathing Apparatus (Others (specify in clear text), Flag State/consul informed) Emergency Escape Breathing Device (Others (specify in clear text), Flag State/consul informed)							
US Coastguard LE	Inspection	2012-07-05	Tampa, Florida	Amy C	United Kingdom	Lloyd's Register Of Shipping	
Vina Del Mar	Inspection	2012-05-11	MEJILLONES	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
Paris MOU	Detailed Inspection	2012-03-21	La Rochelle	Amy-C	United Kingdom	Lloyd's Register	
3 Defects: Propulsion and auxiliary machinery - Auxiliary engine - Inadequate Propulsion and auxiliary machinery - Auxiliary engine - Not as required Propulsion and auxiliary machinery - Other (machinery) - Other							
US Coastguard LE	Inspection	2011-12-15	Tampa, Florida	Amy C	United Kingdom	Lloyd's Register Of Shipping	
US Coastguard	Inspection	2011-12-12	Tampa, Florida	Amy C	United Kingdom	Lloyd's Register Of Shipping	
Vina Del Mar	Inspection	2011-10-27	FORTALEZA CE	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
3 Defects: Other (Deficiency rectified) Other (Deficiency rectified) Emergency Lighting, Batteries and Switches (Deficiency rectified)							
Vina Del Mar	Inspection	2011-10-25	FORTALEZA CE	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
5 Defects: Cargo Ship Safety Equipment Certificate (Others (specify in clear text)) Other (Others (specify in clear text)) Other (Rectify deficiency within 14 days) Fire Fighting Appliances (Rectify deficiency within 14 days) Emergency Lighting, Batteries and Switches (Master instructed to rectify deficiencies before d)							
US Coastguard	Inspection	2010-12-13	Charleston, South Carolina	Amy C	United Kingdom	Lloyd's Register Of Shipping	
3 Defects: POLLUTION PREVENTION/RESPONSE - PREVENTION EQUIPMENT ENGINEERING - FRESHWATER GENERATION SYSTEM LIFESAVING - LIFEBOAT EQUIPMENT							
US Coastguard	Follow up	2010-12-13	Tampa, Florida	Amy C	United Kingdom	Lloyd's Register Of Shipping	
Paris MOU	Detailed Inspection	2010-09-17	Dunkerque	Amy C	United Kingdom	Bureau Veritas	

Authority	Status	Date	Place	Name	Flag	Class	Owner
6 Defects: Safety of navigation - Gyro compass - Not readable ISM related deficiencies - Development of plans for shipboard operations - Missing Fire safety measures - Doors within main vertical zone - Not as required Accident prevention (ILO147) - Protection machines/parts - Missing equipment Accident prevention (ILO147) - Pipes, wires (insulation) - Damaged Safety of navigation - Navigation records - Not as required							
Vina Del Mar	Inspection	2010-02-02	MARACAIBO	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
US Coastguard	Inspection	2010-01-19	Tampa, Florida	Amy C	United Kingdom	Lloyd's Register Of Shipping	
Vina Del Mar	Inspection	2009-05-27	BARRANQUILLA	Amy C	United Kingdom	Lloyds Register	Yaoki Shipping Sa
US Coastguard	Inspection	2009-04-02	Norfolk, Virginia	Amy C	United Kingdom	Bureau Veritas	

5 Defects: FIRE FIGHTING - EMERGENCY FIRE PUMPS LIFESAVING - INFLATABLE LIFERAFTS ELECTRICAL - LIGHTING (EMERGENCY) CONSTRUCTION/LOADLINE - STRUCTURES ACCOMMODATION/OCCUPATIONAL SAFETY - OCCUPATIONAL SAFETY							
Paris MOU	Initial inspection	2008-11-24	Burgas	Amy C	United Kingdom	Bureau Veritas (Bv)	
US Coastguard	Inspection	2008-10-26	Portland, Maine	Amy C	United Kingdom	Bureau Veritas	
Caribbean MOU	Inspection	2008-10-03	Kingston	Amy C	United Kingdom (Uk)	Bureau Veritas	
US Coastguard	Inspection	2008-03-03	Houston, Texas	Amy C	United Kingdom	Bureau Veritas	
US Coastguard	Inspection	2007-06-02	Wilmington, North Carolina	Amy C	United Kingdom	Bureau Veritas	
US Coastguard LE	Inspection	2007-06-01	Wilmington, North Carolina	Amy C	United Kingdom	Bureau Veritas	
Paris MOU	Inspection	2007-01-08	Saint John	Amy C	United Kingdom	Bureau Veritas (Bv)	
US Coastguard	Inspection	2006-10-16	New Orleans, Louisiana	Amy C	United Kingdom	Bureau Veritas	

Safety Management Company

Sequence	Current				
Shipname (Reported)		Flag (Reported)	Isle Of Man	DOC Company	<u>Nova Ship Tech SA</u>
Type	Convention	Auditor	Ri	Issuer	Registro Italiano Na
Date of Issue	2018-06-09	Date of Expiry	2023-06-09		
Sequence	Historical				
Shipname (Reported)		Flag (Reported)		DOC Company	Unknown
Type	Convention	Auditor		Issuer	
Date of Issue	2018-05-09	Date of Expiry			
Sequence	Historical				
Shipname (Reported)	Amy C	Flag (Reported)	Isle Of Man	DOC Company	<u>Nova Ship Tech SA</u>
Type	Convention	Auditor	Rina	Issuer	Rina
Date of Issue	2018-01-18	Date of Expiry	2018-07-17		
Sequence	Historical				
Shipname (Reported)	Amy C	Flag (Reported)	Uk	DOC Company	<u>Carisbrooke Shipping Ltd</u>
Type	Convention	Auditor	Mca	Issuer	Mca
Date of Issue	2006-10-31	Date of Expiry	2011-11-08		
Sequence	Historical				
Shipname (Reported)		Flag (Reported)		DOC Company	Unknown
Type		Auditor		Issuer	
Date of Issue	2006-06-02	Date of Expiry			

Safety Certificates

Casualty & Events

At most, the first fifty Events are returned. Click [here](#) to return the entire list into Search Results.

Event ID	Name at time of Incident	Event Type	Detail	Significance	Start Date
----------	--------------------------	------------	--------	--------------	------------

Construction Overview

ShipType	General Cargo Ship			Built	2006
GT	9,177			Deadweight	13,538

Alterations & Conversion

Arrangement

Structure	Sequence (Bow to Stern)	Position	Type	Material	Length	Breadth
Compartment	01	Centre Or Only	Dry Cargo Hold	Steel (Unspecified)	19.40	
Compartment	02	Centre Or Only	Dry Cargo Hold	Steel (Unspecified)	24.80	
Compartment	03	Centre Or Only	Dry Cargo Hold	Steel (Unspecified)	24.80	
Compartment	04	Centre Or Only	Dry Cargo Hold	Steel (Unspecified)	17.40	
Hatch	01	Centre Or Only	Normal Hatch	N/A	16.10	12.60
Hatch	02	Centre Or Only	Open Hatch	N/A	24.85	17.60
Hatch	03	Centre Or Only	Open Hatch	N/A	24.80	17.60
Hatch	04	Centre Or Only	Normal Hatch	N/A	15.80	17.60
Hatch	05	Centre Or Only	Engine Room	N/A		

Construction Detail

Ship Type Group:General Cargo 10,000-14,999dwt; Statcode5:A31A2GX; Hull Type:Double Sides Entire Compartment Length; Hull Material:Steel; Strengthened for heavy cargoes; Hull Connections:Welded; Decks:1 dk; Bulbous bow;

Recycling Detail (Broken up ships only)

Service Constraints

Shipbuilder

2006-05 [Kyokuyo Shipyard Corp - Shimonoseki YC](#) Yard/hull No.: 463

Sister Ships

At most, the first fifty sister ships are returned. Click [here](#) to return all sister ships into Search Results.

LRNO	Ship Name	Status	Deadweight	GT	Built	Type	Yard No	Main Engine
9331505	SIDER AMY	IN SERVICE/COMMISSION	13538	9177	2006-05	General Cargo Ship	463	7S35MC
9338151	SIDER BILBAO	IN SERVICE/COMMISSION	14184	9177	2007-01	General Cargo Ship	468	7S35MC
9331490	SIDER CARTAGENA	IN SERVICE/COMMISSION	13497	9177	2006-02	General Cargo Ship	462	7S35MC
9528720	SIDER GUYANA	IN SERVICE/COMMISSION	13517	9177	2009-03	General Cargo Ship	492	7S35MC
9528706	SIDER LONDON	IN SERVICE/COMMISSION	13538	9177	2009-09	General Cargo Ship	491	7S35MC
9338149	SIDER VENTURE	IN SERVICE/COMMISSION	13479	9177	2006-12	General Cargo Ship	467	7S35MC

Status History

Date	Status
2006-05-11	In Service/Commission
2006-02-11	Launched
2005-12-02	Keel Laid
2004-04-01	On Order/Not Commenced

Supplementary Features

Feature

Squared Boxed Holds
Fitted for containers
BWMP(E)
Str heavy cargoes
IWS
QUALSHIP 21
Fuel Consumption Speed - Current Value
Total Fuel Consumption - Current Value
Total fuel capacity, in cubic metres
Boiler Manufacturer
Propeller Manufacturer

14.00
21.00
1063.00
Miura
Kamome

Dimensions

Length Overall	136.430	Length (BP)	126.400
Length (Reg)	126.880	Bulbous Bow	Yes
Breadth Extreme	0.000	Breadth Moulded	21.200
Draught	8.350	Depth	11.300
Keel To Mast Height	0.000		
Displacement	17902	T/CM	24.1

Tonnages			
Tonnage Type	One tonnage, unspecified	Tonnage System	New System (International 1969)
Effective Date	2006-05		
Gross Tonnage (GT)	9,177	Net Tonnage (NT)	4,751
Deadweight (DWT)	13,538	Compensated Gross Tonnage (CGT)	0
Formula Deadweight	13,369	Light Displacement Tonnage (LDT)	4,364

Cargo Overview

Grain	17,092	Bale	16,870	Liquid	0	Gas	0
TEU	172	TEU 14t	0	Insulated	0	Passengers	0
Bollard Pull (t)	0						

Capacities

Grain 17,092; Bale 16,870; Segregated Ballast 3,990; TEU: 172

Cargo Handling Gear

2 Cranes of 30 tonnes SWL

Compartments

1 17.40m long Steel (Unspecified) Centre Or Only Dry Cargo Hold(s),1 19.40m long Steel (Unspecified) Centre Or Only Dry Cargo Hold(s),2 24.80m long Steel (Unspecified) Centre Or Only Dry Cargo Hold(s)

Hatches

1 Centre Or Only Open Hatch 24.80m long by 17.60m breadth, 1 Centre Or Only Open Hatch 24.85m long by 17.60m breadth, 1 Centre Or Only Normal Hatch 15.80m long by 17.60m breadth, 1 Centre Or Only Normal Hatch 16.10m long by 12.60m breadth, 1 Centre Or Only Engine Room

Ro-Ro (Lanes, Ramps & Doors)

Specialist

Tanks

Machinery Overview

1 oil engine driving 1 FP propeller at 173 rpm Total Power: Mcr 5,180kW (7,043hp)Max. Speed: 16.00kts, Service Speed: 14.00kts Speed & Consumption: 14.00 knots on 21.00 tonnes per day

Auxiliary Engines

Design: Daihatsu, Engine Builder: Daihatsu 3 x 5DC17, Mcr: 420 kW

Auxiliary Generators

3 x 400kW 450/220V 60Hz a.c.

Boilers

2 x Thermal oil heaters

Bunkers

Fuel: distillate fuel: 94 cu m, residual fuel: 969 cu m


Speed (kn)	At Consumption (t)
14.00	21.00

Prime Mover Detail

Design: MAN-B&W (Group: MAN-B&W), Engine Builder: Makita Corp - Japan1 x 7S35MC, 2 Stroke, Single Acting, In-Line (Vertical)7 Cy. 350 x 1400, Mcr: 5,180 kW (7,043 hp) at 173 rpm

Thrusters

1 Tunnel thruster (f) 526kW(715bhp)



© 2020 IHS Global Limited. IHS Global Limited assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has a contract with IHS Global Limited and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.