: REPORT CREATED AT 8 Oct 2020 13:39

Ship Detail

Ship Name SIDER MOMPOX Shiptype General Cargo Ship IMO/LR No. 9656553 Gross 9,989 Call Sign 3FUY9 Deadweight 14,640 MMSI No. 372321000 Year of Build 2014

Flag Panama Status In Service/Commission

Operator Navesco SA Shipbuilder Ningbo Xinle Shipbuilding

<u>Ownership</u>

Group Owner	Navigest Trust Services	Address Location	Switzerland	Company No.	0519269
Shipmanager	Navigest Trust Services	Address Location	Switzerland	Company No.	0519269
Operator	Navesco SA	Address Location	Colombia	Company No.	0791759
DOC Company	Nova Ship Tech SA	Address Location	Switzerland	IMO Company No (DOC)	5808479
Registered Owner	Nano Shipping Inc	Address Location	Switzerland	IMO Registered Owner No	5758581
Technical Manager	Nova Ship Tech SA	Address Location	Switzerland	Company No.	5808479
Bareboat Owner	Nova Salina SA	Address Location	Panama	Company No.	5995211

Ownership History

Show extended history

Date	Name	Flag	Group Owner	Operator	Manager	Registered Owner	DOC	Price	Seq
2014-12				Navesco SA					00
2014-07							Nova Ship Tech SA		00
2014-07						Nano Shipping Inc			00
2014-07					Navigest Trust Services				00
2014-07			Navigest Trust Services						00
2014-07		Panama							00
2014-07	SIDER MOMPOX								00
2014-07				Sider Navi SpA					94
2014-07						Xinle Hong Kong Holding Co Ltd			95
2014-07					Xinle Hong Kong Holding Co Ltd				95
2014-07				Xinle Hong Kong Holding Co Ltd					95
2014-07			Angel Shipping Hong Kong Co						95

Originally SIDER MOMPOX

Registration, P&I, and Communications

Port of Registry Panama Flag Panama

 Official Number
 4618914B
 Sat Com ID

 Sat Com Ans Back
 Fishing Number

Current P&I Club Standard Club, The

P&I Club History

Date	P&I Club
2017-07-24	Standard Club, The
2014-07-29	GARD AS

Flag, Call Sign & MMSI History

Date	Flag	Port of Registry	Call Sign	MMSI	
2014-07	Panama	Panama	3FUY9	372321000	

AH

1

Three Year Event Summary

Significant Event	Last 12 months	Between 1 and 2 years ago	2-3 years ago
Casualties	0	0	0
Class status changes	0	0	0
Detentions	0	0	0
DOC certificates	0	0	1
Flag changes	0	0	0
Group Owner changes	0	0	0
Inspections	2	3	6
Name changes	0	0	0

Class

Class: Bureau Veritas (IACS) (2014-07-00), Class ID: 16324V BV: Special Survey Date: 2019-08-08 Class Notation: I General cargo ship -heavycargo ([220kn/m2]) -occasional dry bulk cargo CPS(WBT), AUT-UMS, MON-SHAFT, GRABLOADING, INWATERSURVEY Service Restriction: Unrestricted navigation

Class History

Date	Class	Status
2012-11-00	Bureau Veritas (IACS)	(Contemplated)

Surveys

Special Survey Due 2024-07-28, Assigned 2019-08-08, Bureau Veritas Docking Survey Due 2022-08-08, Assigned 2019-08-08, Bureau Veritas

Crew List

Data as of 2020-01-09

Nationality	Total Ratings	Total Officers	Total Crew
Ukranian	4	2	6
Montenegrin	2	2	4
Croatian	0	1	1
Filipino	0	1	1
Kosovan	1	0	1

1

	Status	Date	Place	Name	Flag	Class	Owner
NA 184011	Inspection	2020-09-15	Miami Florida	Sider Mompox	Panama	Bureau Veritas	
Med MOU	Inspection	2019-10-09	Mersin	Sider Mompox	Panama	Bureau Veritas	
Vina Del Mar	Inspection	2019-01-14	BARRANQUILLA	Sider Mompox	Panama	Bureau Veritas	Nova Ship Tech S
Vina Del Mar	Inspection	2019-01-13	BARRANQUILLA	•			Nova Ship Tech S
Safety of Navigation	Conditions - Working Conditio - Radar (Rectified,) - Lights, shapes, sound-sign	_	,				
US Coastguard	Inspection	2018-10-02	New Orleans Louisiana	Sider Mompox	Panama	Bureau Veritas	
	Inspection		BARRANQUILLA				Nova Ship Tech S
Vina Del Mar	Inspection	2018-06-14	BARRANQUILLA				Nova Ship Tech S
3 Defects: Structural condition - Certificates & Docum	Electrical installations in generation - Document - Garbantation - Document - SOPI	age record bo	ok (Rectified,)				· ·
Med MOU	Inspection	2018-05-16	Antalya	Sider Mompox	Panama	Bureau Veritas	
Black Sea MOU	Inspection	2018-03-29	Novorossiisk	Sider Mompox	Panama	Bureau Veritas	
Navigation bridge vis Stowage and provision	ion System (AIS) or (VDR)/Simplified Voyage d sibility on of Lifeboats ures for all gas related instal lation)		S-VDR)				
US Coastguard	Inspection	2017-11-28	Savannah Georgia	Sider Mompox	Panama	Bureau Veritas	
Paris MOU	Initial Inspection	2017-10-30	Karleby (Kokkola)	Sider Mompox	Panama	Bureau Veritas	
Tokyo MOU	Follow up	2017-09-04	Mejillones	Sider Mompox	Panama	Bureau Veritas	
Defect: Gauges,thermomete Gauges,thermomete							
Maintenance of Fire Magnetic compass Lights, shapes, soun Estabilishment of wo inflatable liferafts Auxiliary engine Auxiliary engine Auxiliary engine Auxiliary engine Gauges, thermomete!	rs, etc						
Gauges,thermomete Gauges,thermomete Gauges,thermomete	rs, etc						
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete	rs, etc	2017-07-17	Miami Florida	Sider Mompox	Panama	Bureau Veritas	
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete US Coastguard	rs, etc		Miami Florida Guadeloupe	•		Bureau Veritas Bureau Veritas	
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living O	rs, etc rs, etc Inspection	2017-04-05 ons - Electrica	Guadeloupe	Sider Mompox			
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete US Coastguard Caribbean MOU Defects: Working and Living C Safety of Navigation	rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before	2017-04-05 ons - Electrica ore departure)	Guadeloupe	Sider Mompox	Panama		
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living C Safety of Navigation US Coastguard LE	rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before Inspection	2017-04-05 ons - Electrica ore departure) 2017-02-23	Guadeloupe	Sider Mompox days) Sider Mompox	Panama	Bureau Veritas	
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living C Safety of Navigation US Coastguard LE US Coastguard LE	rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before Inspection	2017-04-05 ons - Electrica ore departure) 2017-02-23	Guadeloupe Il (To be rectified within 14 Port Arthur Texas Lake Charles Louisiana	Sider Mompox days) Sider Mompox Sider Mompox	Panama Panama Panama	Bureau Veritas	
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living C Safety of Navigation US Coastguard LE US Coastguard LE Paris MOU 5 Defects: Life saving appliance Life saving appliance Working and Living C Working and Living C	rs, etc rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before Inspection Inspection	2017-04-05 ons - Electrica ore departure) 2017-02-23 2017-02-23 2016-12-20 structions - Er f liferafts - No ef or rescue bo ons - Entry da	Guadeloupe If (To be rectified within 14 Port Arthur Texas Lake Charles Louisiana Lisboa Atries missing t as required agerous spaces - Missing agerous spaces - Missing	Sider Mompox days) Sider Mompox Sider Mompox Sider Mompox	Panama Panama Panama	Bureau Veritas Bureau Veritas Bureau Veritas	
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living C Safety of Navigation US Coastguard LE US Coastguard LE Paris MOU 5 Defects: Life saving appliance Life saving appliance Life saving appliance US Coastguard LE US Coastguard LE US Coastguard LE OBERCOAST COAST CO	rs, etc rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before Inspection Inspection Detailed Inspection as - On board training and insection Ses - Stowage and provision of ses - Launching arrangements Conditions - Working Conditions	2017-04-05 ons - Electrica ore departure) 2017-02-23 2017-02-23 2016-12-20 structions - Er f liferafts - No ef or rescue bo ons - Entry da	Guadeloupe If (To be rectified within 14 Port Arthur Texas Lake Charles Louisiana Lisboa Intries missing t as required parts - Not as required ingerous spaces - Missing ruments - Not as required	Sider Mompox days) Sider Mompox Sider Mompox Sider Mompox	Panama Panama Panama Panama	Bureau Veritas Bureau Veritas Bureau Veritas Bureau Veritas	Nano Shipping In
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living C Safety of Navigation US Coastguard LE US Coastguard LE Paris MOU 5 Defects: Life saving appliance Life saving appliance Life saving appliance County of the saving and Living C Working and Living C T US Coastguard 3 Defects: FIRE FIGHTING - FIL LIFESAVING - LIFEE	rs, etc rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before Inspection Inspection Detailed Inspection as - On board training and insection so - Stowage and provision of seconditions - Working Conditions - Workin	2017-04-05 ons - Electrica ore departure) 2017-02-23 2017-02-23 2016-12-20 structions - Er f liferafts - No ef or rescue be ons - Entry da ons - Gas inst 2016-10-15 2016-04-25 HING SYSTE	Guadeloupe If (To be rectified within 14 Port Arthur Texas Lake Charles Louisiana Lisboa Intries missing t as required parts - Not as required ngerous spaces - Missing ruments - Not as required CORTES New Orleans Louisiana	Sider Mompox days) Sider Mompox Sider Mompox Sider Mompox Sider Mompox	Panama Panama Panama Panama	Bureau Veritas Bureau Veritas Bureau Veritas Bureau Veritas	Nano Shipping In
Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living C Safety of Navigation US Coastguard LE US Coastguard LE Paris MOU 5 Defects: Life saving appliance Life saving appliance Life saving appliance Working and Living C Vina Del Mar US Coastguard 3 Defects: FIRE FIGHTING - FI. LIFESAVING - LIFEE PERSONNEL - CER	rs, etc rs, etc rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before Inspection Inspection Detailed Inspection as - On board training and insection ses - Stowage and provision of the ses - Stowage and provision of the ses - Launching arrangements Conditions - Working Condition Inspection Inspection XED CO2 FIRE EXTINGUIS BOAT TITIFICATES/DOCUMENTS/L	2017-04-05 ons - Electrica ore departure) 2017-02-23 2016-12-20 structions - Er f liferafts - No sons - Entry da ons - Gas inst 2016-10-15 2016-04-25 HING SYSTE	Guadeloupe If (To be rectified within 14 Port Arthur Texas Lake Charles Louisiana Lisboa Itries missing t as required agerous spaces - Missing ruments - Not as required CORTES New Orleans Louisiana	Sider Mompox days) Sider Mompox Sider Mompox Sider Mompox Sider Mompox Sider Mompox	Panama Panama Panama Panama Panama	Bureau Veritas Bureau Veritas Bureau Veritas Bureau Veritas Bureau Veritas Bureau Veritas	
Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living C Safety of Navigation US Coastguard LE Paris MOU 5 Defects: Life saving appliance Life saving appliance Life saving appliance Life saving appliance Working and Living C Working and Living C Working and Living C Vina Del Mar US Coastguard 3 Defects: FIRE FIGHTING - FI LIFESAVING - LIFEE PERSONNEL - CER	rs, etc rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before Inspection Inspection Detailed Inspection es - On board training and interest of the second training arrangements sonditions - Working Condition Conditions - Working Condition Inspection Inspection XED CO2 FIRE EXTINGUIS BOAT TITIFICATES/DOCUMENTS/L Inspection	2017-04-05 ons - Electrica ore departure) 2017-02-23 2016-12-20 structions - Erf f liferafts - No ors - Entry da ons - Gas inst 2016-10-15 2016-04-25 HING SYSTE ICENSES 2016-01-18	Guadeloupe If (To be rectified within 14 Port Arthur Texas Lake Charles Louisiana Lisboa Intries missing It as required Dats - Not as required Ingerous spaces - Missing It ruments - Not as required CORTES New Orleans Louisiana IM CALLAO	Sider Mompox days) Sider Mompox Sider Mompox sider Mompox Sider Mompox Sider Mompox Sider Mompox	Panama Panama Panama Panama Panama Panama	Bureau Veritas Bureau Veritas Bureau Veritas Bureau Veritas Bureau Veritas Bureau Veritas	Nano Shipping In
Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living C Safety of Navigation US Coastguard LE US Coastguard LIFE saving appliance Life saving appliance Life saving appliance UVINIA DEL MAR US Coastguard 3 Defects: FIRE FIGHTING - FIL LIFESAVING - LIFEE PERSONNEL - CER Vina Del Mar Vina Del Mar	rs, etc rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before Inspection Inspection Detailed Inspection ses - On board training and insection ses - Stowage and provision of ses - Launching arrangements Conditions - Working Condition Conditions - Working Condition Inspection XED CO2 FIRE EXTINGUIS BOAT TITIFICATES/DOCUMENTS/L Inspection Inspection Inspection Inspection	2017-04-05 ons - Electrica ore departure) 2017-02-23 2016-12-20 structions - Err of liferafts - No of for rescue br ons - Gas inst 2016-10-15 2016-04-25 HING SYSTE ICENSES 2016-01-18 2015-08-03	Guadeloupe If (To be rectified within 14 Port Arthur Texas Lake Charles Louisiana Lisboa Intries missing t as required parts - Not as required ngerous spaces - Missing ruments - Not as required CORTES New Orleans Louisiana IM CALLAO BUENAVENTURA	Sider Mompox days) Sider Mompox Sider Mompox sider Mompox instructions Sider Mompox Sider Mompox Sider Mompox Sider Mompox	Panama Panama Panama Panama Panama Panama Panama Panama	Bureau Veritas	
Gauges, thermomete US Coastguard Caribbean MOU 2 Defects: Working and Living C Safety of Navigation US Coastguard LE US Coastguard LIVING C Working and Living C Working and Living C Working and Living C Working and Living C Working LIFES US Coastguard 3 Defects: FIRE FIGHTING - FIL LIFESAVING - LIFEE PERSONNEL - CER Wina Del Mar Wina Del Mar US Coastguard	rs, etc rs, etc rs, etc Inspection Inspection Conditions - Working Condition - Charts (To be rectified before Inspection Inspection Detailed Inspection es - On board training and interest of the second training arrangements sonditions - Working Condition Conditions - Working Condition Inspection Inspection XED CO2 FIRE EXTINGUIS BOAT TITIFICATES/DOCUMENTS/L Inspection	2017-04-05 ons - Electrica ore departure) 2017-02-23 2017-02-23 2016-12-20 structions - Er f liferafts - No of for rescue be ons - Entry da ons - Gas inst 2016-10-15 2016-04-25 HING SYSTE ICENSES 2016-01-18 2015-08-03 2015-01-15	Guadeloupe If (To be rectified within 14 Port Arthur Texas Lake Charles Louisiana Lisboa Intries missing It as required Dats - Not as required Ingerous spaces - Missing It ruments - Not as required CORTES New Orleans Louisiana IM CALLAO	Sider Mompox days) Sider Mompox Sider Mompox sider Mompox instructions Sider Mompox Sider Mompox Sider Mompox Sider Mompox	Panama Panama Panama Panama Panama Panama Panama Panama Panama	Bureau Veritas	Nano Shipping In

′

Safety Management Company

Sequence	Current				
Shipname (Reported)		Flag (Reported)	Panama	DOC Company	Nova Ship Tech SA
Туре	Convention	Auditor	Bv	Issuer	Bureau Veritas
Date of Issue	2017-10-19	Date of Expiry	2022-10-18		
Sequence	Historical				
Shipname (Reported)	Sider Mompox	Flag (Reported)	Panama	DOC Company	Nova Ship Tech SA
Туре	Convention	Auditor	Вv	Issuer	Bv
Date of Issue	2015-09-24	Date of Expiry	2020-05-18		
Sequence	Historical				
Shipname (Reported)	Sider Mompox	Flag (Reported)	Panama	DOC Company	Nova Ship Tech SA
Туре	Convention	Auditor	Bv	Issuer	Bureau Veritas
Date of Issue	2014-11-26	Date of Expiry	2015-05-26		
Sequence	Historical				
Shipname (Reported)		Flag (Reported)	Panama	DOC Company	Nova Ship Tech SA
Туре	Convention	Auditor	Bv	Issuer	Bureau Veritas
Date of Issue	2014-08-08	Date of Expiry	2015-02-08		
Sequence	Historical				
Shipname (Reported)		Flag (Reported)		DOC Company	Unknown
-		Auditor		Issuer	
Type		Additor			

Safety Certificates

Certificate	Issue Date	Expiry Date	Issued By	Inspected
Cargo Ship Safety Construction Certificate	2019-08-08	2024-07-28	Bureau Veritas	2019-10-09 by Med MOU
Cargo Ship Safety Equipment Certificate	2019-08-08	2024-07-28	Bureau Veritas	2019-10-09 by Med MOU
Cargo Ship Safety Radio Certificate	2019-08-08	2024-07-28	Bureau Veritas	2019-10-09 by Med MOU
Document of Compliance (DoC/ISM)	2015-06-22	2020-04-19	Bureau Veritas	2019-10-09 by Med MOU
International Air Pollution Prevention Certificate (IAPP)	2019-08-08	2024-07-28	Bureau Veritas	2019-10-09 by Med MOU
International load Line Certificate	2019-08-08	2024-07-28	Panama	2019-10-09 by Med MOU
International Sewage Pollution Prevention Certificate	2019-08-08	2024-07-28	Bureau Veritas	2019-10-09 by Med MOU
International Ship Security Cetificate (ISSC)	2017-11-09	2022-09-18	Panama	2019-10-09 by Med MOU
Prevention of Pollution by Oil (IOPP)	2019-08-08	2024-07-28	Bureau Veritas	2019-10-09 by Med MOU
Safety Management Certificate (SMC/ISM)	2018-01-26	2022-09-18	Bureau Veritas	2019-10-09 by Med MOU

Casualty & Events

At most, the first fifty Events are returned. Click $\underline{\text{here}}$ to return the entire list into Search Results.

Event ID Name at time of Incident Event Type Detail Significance Start Date

Construction Overview

 ShipType
 General Cargo Ship
 Built
 2014

 GT
 9,989
 Deadweight
 14,640

Alterations & Conversion

Arrangement

Structure	Sequence (Bow to Stern)	Position	Туре	Material	Length	Breadth
Compartment	01	Centre Or Only	Dry Cargo Hold	Steel (Unspecified)		
Compartment	02	Centre Or Only	Dry Cargo Hold	Steel (Unspecified)		
Compartment	03	Centre Or Only	Dry Cargo Hold	Steel (Unspecified)		
Hatch	01	Centre Or Only	Normal Hatch	N/A	22.50	17.50
Hatch	02	Centre Or Only	Normal Hatch	N/A	27.75	17.75
Hatch	03	Centre Or Only	Normal Hatch	N/A	22.50	17.75
Hatch	04	Centre Or Only	Engine Room	N/A		

Construction Detail

Ship Type Group:General Cargo 10,000-14,999dwt; Statcode5:A31A2GX; Standard design:Bestway 12.7; Hull Type:Double Hull; Hull Material:Steel; Strengthened for heavy cargoes; Hull Connections:Welded; Decks:1 dk; Bulbous bow;

Recycling Detail (Broken up ships only)

Service Constraints

Trading, Commercial; Sea, Unspecified

Shipbuilder

2014-07 Ningbo Xinle Shipbuilding Co Ltd - Ningbo ZJ Yard/hull No.: XL-152

Sister Ships

At most, the first fifty sister ships are returned. Click <u>here</u> to return all sister ships into Search Results.

LRNO	Ship Name	Status	Deadweight	GT	Built	Туре	Yard No	Main Engine
<u>9656541</u>	SIDER COLOMBIA	IN SERVICE/COMMISSION	14720	9989	2013-10	General Cargo Ship	XL-151	6DKM-36
9699725	SIDER LIU	IN SERVICE/COMMISSION	14640	9989	2015-04	General Cargo Ship	XL-153	6DKM-36
9656553	SIDER MOMPOX	IN SERVICE/COMMISSION	14640	9989	2014-07	General Cargo Ship	XL-152	6DKM-36
9728849	SIDER TAYRONA	IN SERVICE/COMMISSION	14695	9989	2015-06	General Cargo Ship	XL-154	6DKM-36

Status History

Date	Status
2014-07-29	In Service/Commission
2010-12-12	Keel Laid
2010-09-01	On Order/Not Commenced

Supplementary Features

Feature

BWMP

Squared Boxed Holds PSPC-Water Ballast Tanks

CO2 fitted in holds Str heavy cargoes

IWS

Grab

Total fuel capacity, in cubic metres

Boiler Manufacturer Propeller Manufacturer 705.00

Alfa Laval Aalborg Mitsubishi Heavy

Dimensions

Length Overall	138.900	Length (BP)
Length (Reg)	131.370	Bulbous Bow
Breadth Extreme	21.030	Breadth Moulded
Draught	8.600	Depth
Keel To Mast Height	38.400	
Displacement	19190	T/CM

Tonnages

Tonnage Type	One tonnage, unspecified	Tonnage System	New System (International 1969)
Effective Date	2014-07		
Gross Tonnage (GT)	9,989	Net Tonnage (NT)	5,012
Deadweight (DWT)	14,640	Compensated Gross Tonnage (CGT)	0
Formula Deadweight	13,740	Light Displacement Tonnage (LDT)	4,550

130.000 Yes 21.000 11.400

25.8

Cargo Overview

Grain	17,630	Bale	0	Liquid	0	Gas	0
TEU	0	TEU 14t	0	Insulated	0	Passengers	0
Bollard Pull (t)	0						

Capacities

Grain 17,630; Segregated Ballast 5,220

Cargo Handling Gear

2 Cranes of 30 tonnes SWL

Compartments

3 Steel (Unspecified) Centre Or Only Dry Cargo Hold(s)

Hatches

1 Centre Or Only Normal Hatch 22.50m long by 17.50m breadth, 1 Centre Or Only Normal Hatch 22.50m long by 17.75m breadth, 1 Centre Or Only Normal Hatch 27.75m long by 17.75m breadth, 1 Centre Or Only Engine Room

Ro-Ro (Lanes, Ramps & Doors)

Specialist

Tanks

Machinery Overview

1 oil engine reduction geared to screw shaft driving 1 FP propeller at 150 rpm Total Power: Mcr 3,309kW (4,499hp)Service Speed: 12.60kts

Auxiliary Engines

Auxiliary Generators

3 x 400kW 50Hz a.c.

Boilers

Bunkers

Fuel: distillate fuel: 130 cu m, residual fuel: 575 cu m

Prime Mover Detail

Design: Daihatsu (Group: Daihatsu), Engine Builder: Daihatsu Diesel Manufacturing Co Lt - Japan1 x 6DKM-36, 4 Stroke, Single Acting, In-Line (Vertical)6 Cy. 360 x 480, Mcr: 3,309 kW (4,499 hp) at 600 rpm

Thrusters

1 Tunnel thruster (f)

Photographs

















© 2020 IHS Global Limited. IHS Global Limited assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has a contract with IHS Global Limited and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract